



ARDUINO_Sketch_von_X_Sim

Pin out of arduino for H-Bridge

Pin 10 - PWM1 - Speed for Motor 1.

Pin 9 - PWM2 - Speed for Motor 2.

Pin 2 - INA1 - motor 1 turn

Pin 3 - INB1 - motor 1 turn

Pin 4 - INB1 - motor 2 turn

Pin 5 - INB2 - motor 2 turn

Analog Pins

Pin A0 - input of feedback positioning from motor 1

Pin A1 - input of feedback positioning from motor 2